
AAIB Report: Leonardo AW189 (G-MCGT), Unexpected pitch oscillations

News story

During a brief for a search and rescue (SAR) training flight near Heads of Ayr, a Leonardo AW189 (G-MCGT) experienced unexpected pitch oscillations, 30 July 2021.



During a pre-flight brief for a SAR training flight, the co-pilot highlighted that a previous flight on the aircraft resulted in unexpected pitch oscillations following the selection of the Transition Down mode of the Automatic Flight Control System (AFCS). After other training priorities had been completed, the crew replicated the circumstances that triggered the previous pitch oscillations. The result was similar unexpected flight oscillations in the pitch axis and the crew reported this to the operator.

The event was caused by a shortcoming in the design of the Phase 5 version of the AFCS software SAR upper modes — this also resulted in the incorrect AFCS mode indications being shown to the flight crew and the conflict between airspeed and groundspeed priority on selection of the Transition Down.

Safety Action has been taken by the manufacturer and operator to address the shortcomings in the software, to brief the helicopter community and reinforce the importance of reporting issues.

Read the report.

Media enquiries call: 01932 440015 or 07814 812293

Published 29 September 2022