

## EMSD urges public to stop using 15 models of Ariston and Indesit tumble dryers

The Electrical and Mechanical Services Department today (September 27) urged the public to stop using 15 models of Ariston and Indesit tumble dryers as the manufacturer of the products found a potential risk of fire when excess fluff comes into contact with the dryers' heating element.

The 15 models of tumble dryers concerned were on sale from April 2004. The model numbers are:

Brand		Model Number
1.	Indesit	IDC75EU
2.	Indesit	IDC75UK
3.	Indesit	IS70C
4.	Indesit	ISL60VEX
5.	Ariston	A35VEX
6.	Ariston	AQCF851BUAUS
7.	Ariston	AS600VEX
8.	Ariston	AS60VEX
9.	Ariston	AS700VEX
10.	Ariston	ASL600VEX
11.	Ariston	ASL700CXAG
12.	Ariston	ASL700VEX
13.	Ariston	ASL70CXEX
14.	Ariston	TCF87B6H1AUS
15.	Ariston	TVF75C6H1AUS

Those who have purchased tumble dryers with the aforementioned model numbers should call the service hotline of the product supplier, General Appliance (HK) Ltd, at 3750 9199 to confirm whether their dryers are affected and arrange for product repairs accordingly.

General Appliance (HK) Ltd will publish the repair details of affected products in its website ([www.gahk.com.hk](http://www.gahk.com.hk)) and newspapers tomorrow (September 28).