

HyD receives MTRCL's incident report on construction of reinforced concrete wall at To Kwa Wan Station of Shatin to Central Link

Regarding the incident in which a reinforced concrete wall adjacent to staircases at the To Kwa Wan Station platform under the Shatin to Central Link project was not constructed in accordance with the construction drawings, the Highways Department (HyD) requested the MTR Corporation Limited (MTRCL) on June 11 to submit an incident report with a detailed explanation of the cause of the incident and the rectification plan no later than June 18. The HyD received the report from the MTRCL this morning (June 19), and noted that the MTRCL subsequently made public the report. The department is deeply concerned about the supervision problems revealed in the report. The HyD is scrutinising the details in the MTRCL's report and will request the MTRCL to clarify and provide further information as necessary.