

News story: Derailment at Doncaster



The derailed locomotive

At around 17:17 hrs on 21 December 2018, the third locomotive in a train of four light locomotives derailed at approximately 13 mph (21 km/h). The locomotive had just left Roberts Road depot and was traversing a tight left-hand bend towards Doncaster station. There were no injuries, although some infrastructure was damaged and train services were heavily disrupted.

We have undertaken a [preliminary examination](#) into the circumstances surrounding this accident. Having assessed the evidence which has been gathered to date, we have decided to publish a [safety digest](#).

The safety digest will be made available on our website in the next few weeks.

Published 17 January 2019