

# Report 03/2022: Near miss at Coltishall Lane User Worked Level Crossing, Norfolk, 21 January 2021

## R032022\_220414\_Coltishall

PDF, 5.46 MB, 43 pages

This file may not be suitable for users of assistive technology.

Request an accessible format.

If you use assistive technology (such as a screen reader) and need a version of this document in a more accessible format, please email [enquiries@raib.gov.uk](mailto:enquiries@raib.gov.uk). Please tell us what format you need. It will help us if you say what assistive technology you use.

### **Summary**

At 17:21 hrs on 21 January 2021, a passenger train narrowly avoided a collision with two cars at Coltishall Lane user worked level crossing, near Hoveton, Norfolk. Road traffic over the crossing was higher than usual as a result of drivers seeking a diversionary route for their journeys, following an earlier road traffic accident on a nearby main road.

### [Forward-facing CCTV footage of the near miss at Colitshall UWC, 21 January 2021](#)

The safe use of the crossing relied solely on telephones to warn users in road vehicles of approaching trains, and the near miss occurred because the car drivers did not telephone the signaller before using the crossing. The investigation found that this may have been because the car drivers were unfamiliar with the crossing, because the signs at the crossing were ineffective in prompting users on how to cross safely, and because the level crossing gates had already been opened. It is also possible that factors such as the increased level of road traffic may have affected the behaviour of road users and their decision-making.

The investigation also found that Network Rail and its predecessors had not taken measures to close or upgrade this crossing, despite being aware of the risks it posed. This was possibly because Network Rail's processes for assessing and controlling risk at the crossing did not take account of some of the factors present, leading to an incomplete understanding of the risks involved in its operation. Additionally, the status of user worked crossings on public roads was not acknowledged within relevant statutory provisions and industry guidance, and this may have affected how safety at these crossings was managed by infrastructure managers. The Office of Rail and Road had previously taken regulatory action, but this had not resulted in action by

Network Rail to address the risk at this crossing by the time the near miss occurred.

## **Recommendations**

RAIB's report makes three recommendations. The first is that Network Rail should assess, and if necessary reduce, the risks of incidents and accidents at vehicular user worked crossings which may see significant use by unfamiliar users, consistent with current industry best practice. The second is that Network Rail, in consultation with the Office of Rail and Road and the Department for Transport, should improve signage at user worked crossings which may share features identified in this investigation. The third is that the Department for Transport, in consultation with the Office of Rail and Road and Network Rail, should evaluate the extent to which recent guidance on the drafting and making of level crossing orders will better enable the implementation of improved safety measures at level crossings.

There is one learning point that reminds those responsible for the management of safety of user worked crossings to adhere to the principles of level crossing risk assessment published by ORR in June 2021.

### **Andrew Hall, Chief Inspector of Rail Accidents said:**

"This very near miss involved two road vehicles and took place at a user worked level crossing on a public road. Level crossings are one of the biggest sources of risk on the UK's railways. RAIB has investigated many accidents and incidents over the last sixteen years and noted considerable improvement in the way risk at many types of level crossing is managed. However, we feel at present the greatest scope for safety improvement exists at user worked crossings, whether on private or public roads. The significant number of such crossings on public roads is of concern because most motorists are unlikely to be familiar with the concept of a level crossing which they must operate themselves. Because of this, they may not use the crossing safely as was the case in this incident. Over more than 20 years, the railway was aware that the safety arrangements at this crossing should be improved, but it seems that bringing about such change was too difficult. The regulatory structure in place to oversee level crossing safety did not result in action being taken at this crossing in time to avoid this incident.

"Our recommendations seek to promote safety improvements at user worked crossings on public roads and to check that regulatory actions being taken to make such improvements easier to achieve have the desired effect."

## **Notes to editors**

1. The sole purpose of RAIB investigations is to prevent future accidents and incidents and improve railway safety. RAIB does not establish blame, liability or carry out prosecutions.
2. RAIB operates, as far as possible, in an open and transparent manner. While our investigations are completely independent of the railway industry, we do maintain close liaison with railway companies and if we discover matters that may affect the safety of the railway, we make sure

that information about them is circulated to the right people as soon as possible, and certainly long before publication of our final report.

3. For media enquiries, please call 01932 440015.

**Newsdate: 14 April 2022**