

Safety bulletin 4/2024 published

Owners, operators and skippers of fishing vessels fitted with side shell doors urged to ensure suitable and sufficient risk assessment of watertight integrity.