

Taw and Torridge Coaches fined for diesel leak into Taw estuary

Company boss Mark Hunt consistently denied any wrongdoing and blamed pollution on nearby petrol station. But coach depot fuel pumps had not been calibrated.