

# Anniversary Statement: Leonardo AW139, G-CIMU, 13 June 2022

Tail rotor duplex bearing failure found during post-flight maintenance,  
Norwich Airport, 13 June 2022