## EMSD is deeply concerned about train door detachment incident of MTR Tsuen Wan Line

The Electrical and Mechanical Services Department (EMSD) is deeply concerned about the incident involving door detachment of an MTR Tsuen Wan Line train today (November 13) morning and has immediately commenced investigation, including visit to the place of incident and the train concerned. The EMSD will examine various factors, including foreign objects and conditions of mechanical parts.

The EMSD has also required the MTR Corporation to submit incident report as soon as possible, and duly formulate and implement improvement measures to ensure the safety of railway operation.