

Notice: Cotterstock Lock downstream landing stage

When: until further notice.

What's happening: part of the downstream landing stage is out of use due to unstable ground at the rear.

Notice: Upstream of Cotterstock Lock

When: until further notice.

What's happening: there is a fallen tree completely blocking the navigation upstream of Cotterstock Lock.

Research and analysis: Water situation: area monthly reports for England 2018

Updated: September reports uploaded.

These reports collect information from the Environment Agency, the Met Office and water companies that measure and monitor:

- the amount of rain that falls
- how dry the soils are and how much rain they can soak up
- the amount of water flowing in rivers
- the amount of water stored below ground in aquifers and above ground in reservoirs

They also present the outlook for river flow and groundwater.

Notice: Upper Wellingborough downstream canoe portage

When: until further notice.

What's happening: due to health and safety concerns the canoe portage is closed.

Notice: Denford Lock

When: until further notice.

What's happening: please be aware there is a gravel shoal located approximately 30 metres downstream of Denford Lock.