

Managing director receives suspended sentence after worker is burned in petrol tank explosion

A managing director has received a suspended sentence after an employee suffered severe burns on a construction site in Swynecombe, Henley-on-Thames, Oxfordshire.

Milton Keynes Magistrates Court heard how managing director of MWJ Construction Ltd, Marcin Wojtas failed to take reasonably practicable precautions for the decommissioning of a petrol tank, which resulted in an explosion.

An investigation by the Health and Safety Executive (HSE) into the incident that occurred on 9 July 2018, found that the injured person and another operative were instructed by Mr Wojtas to use an angle grinder to remove the tank lid to speed up the decommissioning of the tank. While performing this task, the petrol vapours within the tank were ignited and an explosion occurred. The injured person sustained burns to 26 per cent of their body.

The investigation also found Mr Wojtas had been informed by an officer from the Petroleum Enforcing Authority that the work to decommission the fuel tank was a specialised operation and needed to be completed by a competent contractor. Neither operative had any of the training, experience or knowledge required to make them competent.

Marcin Wojtas of Hatfield Road, London pleaded guilty to breaching section 37 of the Health and Safety at Work etc. Act 1974. He was given a six month suspended sentence and ordered to pay total costs of £8,455.48.

Speaking after the hearing, HSE inspector David Tonge said: "The accident could have been prevented if the work was appropriately planned through an adequate risk assessment. Had this been the case, competent operatives would have conducted the work, the tank would have had its hazardous contents (petrol vapour and petrol) removed safely and equipment appropriate to use around an explosive atmosphere would have been used."

Notes to Editors:

1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. We prevent work-related death, injury and ill health through regulatory actions that range from influencing behaviours across whole industry sectors through to targeted interventions on individual businesses. These activities are supported by globally recognised scientific expertise. www.hse.gov.uk
2. HSE news releases are available at <http://press.hse.gov.uk>
3. For HSE's working safely guidance see <https://www.hse.gov.uk/coronavirus/working-safely/index.htm>

The post [Managing director receives suspended sentence after worker is burned in petrol tank explosion](#) appeared first on [HSE Media Centre](#).

[Company fined after worker suffered serious facial injuries](#)

Manufacturing company, Acrivarn Ltd, was sentenced today for safety breaches after an employee using a 9-inch angle grinder suffered significant facial injuries when the cutting disc came into contact with his face.

Huddersfield Magistrates' Court heard how, on 23 July 2019, the injured person had been assigned the task of dismantling a mezzanine spray booth steel structure in the assembly workshop. To cut through the thicker parts of the steel structure he was using a Bosch nine-inch angle grinder with a steel-cutting disc attached. This equipment requires two hands to operate it.

In order to cut the steel on the higher parts of the booth the employee was using a stepladder and had attached himself to the hook of an overhead crane with a fall restraint harness he was wearing.

When he was standing on the ladder, attempting to cut through a piece of angled steel beam, the grinder kicked back at him and the cutting disc made contact with his face.

The cutting disc caused a deep laceration under his chin, through into his mouth which required 52 stitches. Nerves in his face were damaged, which caused a loss of feeling and movement in his lips and chin. He narrowly escaped making contact with his jugular vein.

An investigation by the Health and Safety Executive (HSE) found that the employee had only used the nine-inch angle grinder on one other occasion during his employment with Acrivarn Ltd and had never used it when working at height. At the time of the incident, Acrivarn Ltd had access to more appropriate oxyacetylene cutting equipment and trained operators of such equipment on site.

Acrivarn Ltd of South Park Mills, Hare Lane, Pudsey Leeds pleaded guilty to breaching Section 2 (1) of the Health & Safety at Work etc. Act 1974. The company has been fined £24,000 and ordered to pay £1,412.24 in costs.

Speaking after the hearing, HSE inspector David Beaton said: "There was a significant risk of the angle grinder kicking back when cutting through the angled steel.

"Using the grinder at height affected the user's ability to resist kickback forces and placed him in a dangerous position.

"Working at height and demolition work needs to be properly planned, suitably

and sufficiently assessed and the most appropriate equipment selected for the job.”

Notes to Editors:

1. The Health and Safety Executive (HSE) is Britain’s national regulator for workplace health and safety. We prevent work-related death, injury and ill health through regulatory actions that range from influencing behaviours across whole industry sectors through to targeted interventions on individual businesses. These activities are supported by globally recognised scientific expertise. www.hse.gov.uk
2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
3. HSE news releases are available at <http://press.hse.gov.uk>

The post [Company fined after worker suffered serious facial injuries](#) appeared first on [HSE Media Centre](#).

[Builder fined after contractor suffers life-changing injuries in fall from roof](#)

A builder has been sentenced after a contractor fell eight metres from a roof at a site in Hove.

Brighton Magistrates Court heard how on the 28 June 2019, Mark Bucknall was working with another man to install rooflights to the flat roof of a loft conversion in Hove. To access the roof, they had to climb out of a window and up the original tiled roof.

When returning inside the property, the worker slipped and fell landing in the concrete yard of the neighbouring property. He sustained multiple fractures to his spine and right leg, and a fractured left heel and wrist. He is still recovering from the injuries and it is unknown if he will regain mobility.

An investigation by the Health and Safety Executive found that the work was not properly planned. Earlier in the project, scaffold had been erected, but it was removed before the rooflights were delivered. No consideration was given to falling from the edge of the flat roof whilst installing the rooflights, or how they would safely access the roof.

Mark Bucknall of Holmes Avenue, Hove pleaded guilty to breaching Section 37 (1) of the Health and Safety at Work etc. Act 1974 and was fined £1,760, ordered to pay £2,000 costs and £170 victim surcharge.

Speaking after the hearing, HSE inspector Stephen Green, said “The worker’s injuries are life changing and he could have easily been killed. This serious incident and devastation could have been avoided if basic means to enable safe access and prevent falls, such as the scaffolding used earlier in the project, had been in place.”

Notes to Editors:

1. The Health and Safety Executive (HSE) is Britain’s national regulator for workplace health and safety. We prevent work-related death, injury and ill health through regulatory actions that range from influencing behaviours across whole industry sectors through to targeted interventions on individual businesses. These activities are supported by globally recognised scientific expertise. www.hse.gov.uk
2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
3. HSE news releases are available at <http://press.hse.gov.uk>

The post [Builder fined after contractor suffers life-changing injuries in fall from roof](#) appeared first on [HSE Media Centre](#).

[Company fined after subcontractor falls from height](#)

Solar panel company Blue Sun Energy Limited was sentenced today for safety breaches after a self-employed labourer fell through a rooflight.

Leeds Magistrates’ Court heard that on 13 December 2018, the 34-year-old, was working on behalf of and under the control of Blue Sun Energy Ltd when he fell approximately 3.5 metres through an unmarked and unguarded fragile surface (rooflight) into the shed below.

An investigation by the Health and Safety Executive (HSE) found that the worker was undertaking snagging work relating to the installation of solar panels on the roof of a cowshed at Home Farm Gargrave, Skipton. He stepped onto one of the roof lights and fell through it. He suffered a traumatic brain injury, fractured shoulder and severe bruising. He has yet to return to work.

Blue Sun Energy Limited of Avenue Road, Queniborough, Leicester pleaded guilty to breaching Section 3 (1) of the Health & Safety at Work etc Act 1974. The company has been fined £38,019 and ordered to pay £1,071 in costs.

Speaking after the hearing, HSE inspector Ben Caines said: "Falls from height often result in life-changing or fatal injuries. In most cases, these incidents are needless and could be prevented by properly planning the work to ensure that effective preventative and protective measures are in place such as edge protection or coverings built to the correct standard.

"This incident could have easily been prevented if the company had installed adequate edge protection or covered the opening to prevent falls."

Notes to Editors:

1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. We prevent work-related death, injury and ill health through regulatory actions that range from influencing behaviours across whole industry sectors through to targeted interventions on individual businesses. These activities are supported by globally recognised scientific expertise. www.hse.gov.uk
2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
3. HSE news releases are available at <http://press.hse.gov.uk>

The post [Company fined after subcontractor falls from height](#) appeared first on [HSE Media Centre](#).

[Recycling company fined after worker suffered life threatening injuries](#)

EPS Materials Recovery Limited has been fined after a worker suffered injuries to his face and head when he was struck by a ball of compressed metal weighing approximately half a tonne. The metal was being used as a brush attached to the grab of a 360 degree excavator machine.

Swansea Magistrates' Court heard how on 8 May 2019, the employee was working in the vicinity of the grab machine. The driver swung the arm to the location of the employee and dropped the brush, in doing this the brush fell onto the worker striking him on the back and causing him to hit the floor with force. He suffered a fractured skull, a fractured eye-socket and fractured cheek bone.

An investigation by the Health and Safety Executive (HSE) found the company failed to adequately segregate pedestrians and operating vehicles. Site induction procedures and training for new starters was inadequate. There wasn't any direct supervision for new starters to prevent access to the dangerous parts of machinery or to stop dangerous parts before access was gained.

EPS Materials Recovery Limited of Griagola Wharf, King's Dock, Swansea, was found guilty of breaching Section 2(1) of the Health and Safety at Work etc Act 1974 and were fined £300,000 and ordered to pay costs of £7,059.

Speaking after the hearing, HSE inspector Wayne Williams, said: "Those in control of work have a responsibility to devise safe methods of working and to provide the necessary information, instruction and training to their workers in the safe system of work.

"There is industry-produced guidance for this type of activity, which demonstrates how short the company fell of the required standard. If a suitable safe system of work had been in place prior to the incident, the life changing injuries sustained by the employee could have been prevented."

The industry guidance for Hand sorting of Recyclables (Totting) with Vehicle Assistance can be found here:

<https://wishforum.org.uk/wp-content/uploads/2017/02/WASTE-18-.pdf>.

Notes to Editors:

1. The Health and Safety Executive (HSE) is Britain's national regulator for workplace health and safety. We prevent work-related death, injury and ill health through regulatory actions that range from influencing behaviours across whole industry sectors through to targeted interventions on individual businesses. These activities are supported by globally recognised scientific expertise. www.hse.gov.uk
2. More about the legislation referred to in this case can be found at: www.legislation.gov.uk/
3. HSE news releases are available at <http://press.hse.gov.uk>

The post [Recycling company fined after worker suffered life threatening injuries](#) appeared first on [HSE Media Centre](#).